

CHANGELOG

1.0.3-ga1 | 2022-11-24

Added

- [#128] Added function for internal diagnosis of touch sensor

Changed

- [#135] Changed website does not perform automatic restart upon firmware update or factory reset
- [#134] Changed internal error code structure

Fixed

- [#136] Fixed scenario does not start from the beginning when it has been previously interrupted
- [#133] Fixed firmware update via service center fails when using certain browsers
- [#131] Improved restrictions for the access of the service center
- [#130] Fixed lamp does not stay at lowest brightness at the end of relax mode
- [#129] Improved restrictions for the access via inio app

1.0.2-ga1 | 2022-11-17

Added

- [#122] Introduction of new release versioning scheme
- [#111] Add error signal for incompatible power adapter

Changed

- [#119] Renamed "Update Center" to "Service Center"
- [#117] Bumped build toolchain to v4.4.3
- [#115] HCL profile is not automatically executed upon power-on

Fixed

- [#126] WebUI displays release identifier
- [#125] Missing German translation in footer of WebUI
- [#124] Empty error list for long-running device
- [#123] Persistent error is spamming the error list
- [#121] Exit HCL mode through tap on connect button not possible
- [#120] Device is leaving HCL mode unintended
- [#118] Fast flicker in HCL mode at low dimming value
- [#113] Exit from AP-mode does not lead to standby mode
- [#110] Unexpected restart toggling Bluetooth connectability
- [#108] Light flash during pairing (lamp was paired before)

1.0.1 | 2022-11-08

Changed

- [#95] Changed BT discovery name from "inioLight" to "inio-one"
- [#109] Changed WiFi SSID from "inio_one-xxxx" to "inio-one-xxxx"
- [#107] Changed firmware downgrade is not longer possible in production releases

Fixed

- [#77] Fixed slider LEDs sometimes are off (not deterministic)
- [#97] Fixed relax button has less touch sensitivity compared to other buttons
- [#101] Fixed DE|EN language selector is sometimes clipped in WebUI
- [#106] Fixed two possibilities to trigger lamp into AP-mode

1.0.0 | 2022-10-07

- Initial release